



**Application: Application: Aplicación:**

Nissan Maxima | Infiniti I30, I35



*Caution or service label will be on glove box door if vehicle is equipped with cabin filter.*

**Location of filter:**

On the passenger side of the vehicle behind the glove compartment door.

**Tools:**

Needle-nose pliers and a #2 Phillips  
Screwdriver

**To remove existing filter:**

1. With glove compartment closed locate and remove the two screws and or the clips and lower glove compartment finisher located at the bottom of the glove compartment.
2. Open the glove compartment, locate and remove the four plastic screws at the top of the glove compartment frame including the screws securing the glove compartment latch.
3. Allow the glove compartment to swing downward and disconnect the glove compartment light by pushing in on the tab and removing.

***DO NOT DISCONNECT THE YELLOW AIR BAG CONNECTORS FROM EACH OTHER OR ALLOW THE GLOVE COMPARTMENT TO HANG FROM OR STRESS THE YELLOW AIR BAG CONNECTION OR WIRES.***

4. Do not disconnect the yellow air bag connectors, instead remove the whole connection assembly by squeezing the little plastic tabs securing the assembly to the bracket.
5. Locate the cabin filter cover and remove the cover by pushing down on the metal clip at the bottom of the cover until it pops off.
6. Remove the cabin filter cover by sliding the plastic cap up and remove the cover from the fixation at the top.
7. Remove the dirty filter.
8. Replace the dirty filter with the two filters making sure that the air flow directional arrows are in the correct direction and that the two filters stack in place correctly to replace the original filter.
9. Reverse steps 1-6 to complete installation.